

Piston-type valve - impossible to grab a directly representative sample

Parts in red are in contact with the application. Even when the valve is fully closed, there are parts that need to be cleaned/flushed to prevent cross-contamination and/or plugging. With piston-type valve, cleaning this area is not possible, thus preventing to grab a directly representative sample.

